| Last Modified: 12-04-2024  | 6.11:8.1.0         | <b>Doc ID:</b> RM1000000289NH |  |  |
|--|--------------------|-------------------------------|--|--|
| Model Year Start: 2023   | Model: Prius Prime | Prod Date Range: [12/2022 - ] |  |  |
| Title: ADVANCED DRIVER ASSISTANCE SYSTEM: FRONT SIDE RADAR SENSOR SYSTEM: U123687; Lost                      |                    |                               |  |  |
| Communication with Cruise Control Front Distance Range Sensor Front Side "B" Missing Message; 2023 - 2024 MY |                    |                               |  |  |
| Prius Prius Prime [12/2022 - ]   |                    |                               |  |  |


DTC U123687 Lost Communication with Cruise Control Front Distance Range Sensor Front Side "B" Missing Message

## **DESCRIPTION**

When the front side radar sensor (A) detects a communication malfunction with the front side radar sensor (B), this DTC is stored.

| DTC NO. | DETECTION ITEM   | DTC DETECTION<br>CONDITION  | TROUBLE AREA | DTC<br>OUTPUT             | PRIORITY |
|---------|--|---|--------------|---------------------------|----------|
| U123687 | Lost Communication with<br>Cruise Control Front<br>Distance Range Sensor Front<br>Side "B" Missing Message | The front side radar sensor (A) does not receive communication from the front side radar sensor (B) |              | FROM Front Side Radar "A" | A        |

## **WIRING DIAGRAM**



## **CAUTION / NOTICE / HINT**

### **NOTICE:**

- When checking for DTCs, make sure that the pre-collision system is turned on.
- After replacing the front side radar sensor, make sure to perform ECU writing.

Click here NFO

• After replacing the front side radar sensor, make sure to perform front side radar sensor beam axis alignment and clear all stored vehicle control history of each system.

#### HTNT:

Front side radar sensor beam axis alignment can be performed by using "Triangle Target", "Driving Adjustment" or "ECU DATA SAVE/WRITE".

Triangle Target: NFO

Driving Adjustment: NFO

ECU DATA SAVE/WRITE: NFO

• After the ignition switch is turned off, there may be a waiting time before disconnecting the negative (-) auxiliary battery terminal.

Click here NFO

#### HINT:

When disconnecting and reconnecting the auxiliary battery, there is an automatic learning function that completes learning when the respective system is used.

Click here NFO

#### HINT:

- Before disconnecting each connector for inspection, push in on the connector case to check that each connector is not loose or disconnected.
- When a connector is disconnected, check that the terminals and connector case are not cracked, deformed or corroded.
- If a DTC is stored again after being cleared, the malfunction may be occurring due to vibration of the vehicle. In this case, wiggle an ECU or wire harness to check if a malfunction occurs.

## **PROCEDURE**

CHECK CAN MAIN WIRE (FRONT SIDE RADAR SENSOR (B))

Pre-procedure1

1.

- (a) Disconnect the cable from the negative (-) auxiliary battery terminal.
- (b) Disconnect the A42 front side radar sensor (B) connector.

Procedure1

(c) Measure the resistance according to the value(s) in the table below.

Standard Resistance:



Click Location & Routing(A42)
Click Connector(A42)

| TESTER CONNECTION              | CONDITION   | SPECIFIED<br>CONDITION | RESULT |
|--------------------------------|---|------------------------|--------|
| A42-5 (CA2P) - A42-6<br>(CA2N) | Cable disconnected from negative (-) auxiliary battery terminal | 108 to 132 Ω           | Ω      |

| TESTER CONNECTION             | CONDITION   | SPECIFIED<br>CONDITION | RESULT |
|-------------------------------|---|------------------------|--------|
| A42-5 (CA2P) - Body<br>ground | Cable disconnected from negative (-) auxiliary battery terminal | 200 Ω or higher        | Ω      |
| A42-6 (CA2N) - Body<br>ground | Cable disconnected from negative (-) auxiliary battery terminal | 200 Ω or higher        | Ω      |
| A42-5 (CA2P) - +B             | Cable disconnected from negative (-) auxiliary battery terminal | 6 kΩ or higher         | kΩ     |
| A42-6 (CA2N) - +B             | Cable disconnected from negative (-) auxiliary battery terminal | 6 kΩ or higher         | kΩ     |

Post-procedure1

(d) None





## 2. CHECK FRONT SIDE RADAR SENSOR (B)

Pre-procedure1

- (a) Connect the A42 front side radar sensor (B) connector.
- (b) Disconnect the A41 front side radar sensor (A) connector.

Procedure1

(c) Measure the waveform according to the value(s) in the table below.

Standard:



# Click Location & Routing(A41) Click Connector(A41)

| TESTER CONNECTION           | CONDITION          | TOOL SETTING           | SPECIFIED CONDITION |
|-----------------------------|--------------------|------------------------|---------------------|
| A41-5 (CA2P) - A41-6 (CA2N) | Ignition switch ON | 1 V/DIV., 100 μs./DIV. | Pulse generation    |

Post-procedure1

(d) None



NG > REPLACE FRONT SIDE RADAR SENSOR (B)

## 3. CHECK CAN MAIN WIRE (FRONT SIDE RADAR SENSOR (A))

### Pre-procedure1

- (a) Connect the A42 front side radar sensor (B) connector.
- (b) Disconnect the A41 front side radar sensor (A) connector.

#### Procedure1

(c) Measure the resistance according to the value(s) in the table below.

Standard Resistance:



# Click Location & Routing(A41) Click Connector(A41)

| TESTER CONNECTION              | CONDITION   | SPECIFIED<br>CONDITION | RESULT |
|--------------------------------|---|------------------------|--------|
| A41-5 (CA2P) - A41-6<br>(CA2N) | Cable disconnected from negative (-) auxiliary battery terminal | 108 to 132 Ω           | Ω      |
| A41-5 (CA2P) - Body<br>ground  | Cable disconnected from negative (-) auxiliary battery terminal | 200 Ω or higher        | Ω      |
| A41-6 (CA2N) - Body<br>ground  | Cable disconnected from negative (-) auxiliary battery terminal | 200 Ω or higher        | Ω      |
| A41-5 (CA2P) - +B              | Cable disconnected from negative (-) auxiliary battery terminal | 6 kΩ or higher         | kΩ     |
| A41-6 (CA2N) - +B              | Cable disconnected from negative (-) auxiliary battery terminal | 6 kΩ or higher         | kΩ     |

Post-procedure1

(d) None

OK > REPLACE FRONT SIDE RADAR SENSOR (A)





