| | J |
|--|---|

| Last Modified: 12-04-2024 | 6.11:8.1.0 | Doc ID: RM100000029ZLM | | |
|---|--------------------|-------------------------------|--|--|
| Model Year Start: 2023 | Model: Prius Prime | Prod Date Range: [12/2022 -] | | |
| Title: M20A-FXS (ENGINE CONTROL): KNOCK SENSOR: REMOVAL; 2023 - 2024 MY Prius Prius Prime [12/2022 -] | | | | |

REMOVAL

CAUTION / NOTICE / HINT

The necessary procedures (adjustment, calibration, initialization or registration) that must be performed after parts are removed and installed, or replaced during knock control sensor removal/installation are shown below.

Necessary Procedures After Parts Removed/Installed/Replaced

| REPLACED PART OR PERFORMED PROCEDURE | NECESSARY PROCEDURE | EFFECT/INOPERATIVE FUNCTION WHEN NECESSARY PROCEDURE NOT PERFORMED | LINK |
|---|-------------------------|---|------|
| Replacement of knock control sensor Replacement of throttle body with motor assembly Cleaning the deposits from the throttle body with motor assembly Gas leak from exhaust system is repaired | Inspection after repair | Poor idle, etc.Engine start function, etc. | INFO |

NOTICE:


This procedure includes the removal of small-head bolts. Refer to Small-Head Bolts of Basic Repair Hint to identify the small-head bolts.

Click here

CAUTION / NOTICE / HINT

COMPONENTS (REMOVAL)





| | PROCEDURE | PART NAME CODE | ! | | \$ |
|---|----------------------|----------------|------|---|-----------|
| 1 | INTAKE MANIFOLD | 17111 | - | - | - |
| 2 | KNOCK CONTROL SENSOR | 89615 | INFO | - | - |

PROCEDURE

1. REMOVE INTAKE MANIFOLD

Click here

2. REMOVE KNOCK CONTROL SENSOR



NOTICE:

If the knock control sensor has been struck or dropped, replace it.

