Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM10000002C018		
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [03/2023 -]		
Title: POWER DISTRIBUTION: INTEGRATION CONTROL SUPPLY: REMOVAL; 2023 - 2024 MY Prius Prius Prime				
[03/2023 -]				

REMOVAL

CAUTION / NOTICE / HINT

The necessary procedures (adjustment, calibration, initialization or registration) that must be performed after parts are removed and installed, or replaced during integration control supply removal/installation are shown below.

NOTICE:

- When disconnecting a wire harness of any component connected to the supply power of the integrated capacitor (integration control supply) or when removing the integrated capacitor (integration control supply), make sure to wait 5 minutes or more after turning the ignition switch off for self-diagnosis to complete and the voltage of the integrated capacitor (integration control supply) to discharge.
- After turning the ignition switch off, waiting time may be required before disconnecting the cable from the negative (-) auxiliary battery terminal.



HINT:

When the cable is disconnected/reconnected to the auxiliary battery terminal, systems temporarily stop operating. However, each system has a function that completes learning the first time the system is used.

Items for which learning is completed by driving the vehicle

EFFECT/INOPERATIVE FUNCTION WHEN NECESSARY PROCEDURES ARE NOT PERFORMED	NECESSARY PROCEDURES	LINK
Front Camera System	Drive the vehicle straight ahead at 35 km/h (22 mph) or more for 5 second or more.	INFO


Items for which learning is completed by operating the vehicle normally

Power Door Lock Control System*1 Back door opener Perform door unlock operation with door control switch or electrical key transmitter sub-assembly switch. Power Back Door System*2 Reset back door close position for HEV Model: After the ignition switch is turned to ON, the servo motor standard position is recognized. After the ignition switch is turned to ON, the servo motor and expansion valve standard position is recognized.	EFFECT/INOPERATIVE FUNCTION WHEN NECESSARY PROCEDURES ARE NOT PERFORMED	NECESSARY PROCEDURES	LINK
for HEV Model: After the ignition switch is turned to ON, the servo motor standard position is recognized. Air Conditioning System for PHEV Model: After the ignition switch is turned to ON, the servo motor and expansion valve standard	·	switch or electrical key transmitter sub-assembly	INFO
After the ignition switch is turned to ON, the servo motor standard position is recognized. Air Conditioning System for PHEV Model: After the ignition switch is turned to ON, the servo motor and expansion valve standard	Power Back Door System*2	Reset back door close position	INFO
	Air Conditioning System	After the ignition switch is turned to ON, the servo motor standard position is recognized. for PHEV Model: After the ignition switch is turned to ON, the servo motor and expansion valve standard	-

*2: w/ Power Back Door System

CAUTION / NOTICE / HINT

COMPONENTS (REMOVAL)



	PROCEDURE	PART NAME CODE	!		
1	DISCONNECT CABLE FROM NEGATIVE AUXILIARY BATTERY TERMINAL	-	-	-	-
2	REAR CONSOLE BOX ASSEMBLY	58910C	INFO	-	-
3	INTEGRATION CONTROL SUPPLY	28912	-	-	-
4	NO. 1 INTEGRATION CONTROL SUPPLY BRACKET	28911	-	-	-
5	NO. 2 INTEGRATION CONTROL SUPPLY BRACKET	28911A	-	-	-
6	INTEGRATION CONTROL COVER	28913	-	-	-

•	Non-reusable part	-	-

PROCEDURE


1. DISCONNECT CABLE FROM NEGATIVE AUXILIARY BATTERY TERMINAL

- (a) for M20A-FXS:
 - Click here
- (b) for 2ZR-FXE:
 - Click here

2. REMOVE REAR CONSOLE BOX ASSEMBLY




3. REMOVE INTEGRATION CONTROL SUPPLY




Remove in this Direction	_	-	
--------------------------	---	---	--

- (1) Disconnect the connector.
- (2) Remove the 2 bolts.
- (3) Slide the integration control supply as shown in the illustration to remove it.

4. REMOVE NO. 1 INTEGRATION CONTROL SUPPLY BRACKET



5. REMOVE NO. 2 INTEGRATION CONTROL SUPPLY BRACKET



6. REMOVE INTEGRATION CONTROL COVER

HINT:

Perform this procedure only when replacement of the integration control cover is necessary.

