

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000028U0V
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: CELLULAR COMMUNICATION: SAFETY CONNECT SYSTEM: B15A804; DCM System Internal Failure; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

DTC	B15A804	DCM System Internal Failure
------------	----------------	------------------------------------

DESCRIPTION

This DTC is stored when an internal circuit malfunction is detected by the DCM (telematics transceiver) self check.

DTC NO.	DETECTION ITEM	DTC DETECTION CONDITION	TROUBLE AREA	DTC OUTPUT FROM	PRIORITY
B15A804	DCM System Internal Failure	DCM (telematics transceiver) internal malfunction	DCM (telematics transceiver)	Telematics	A

CAUTION / NOTICE / HINT

NOTICE:

- Regardless of whether DTC B15A804 has been output as a present or history DTC, the DCM (telematics transceiver) should be replaced.
- Depending on the parts that are replaced during vehicle inspection or maintenance, performing initialization, registration or calibration may be needed. Refer to Precaution for Safety Connect System.

Click here 

PROCEDURE

1.	REPLACE DCM (TELEMATICS TRANSCEIVER)
-----------	---

(a) Replace the DCM (telematics transceiver) with a new one.

HINT:

Click here 

NOTICE:

- The ignition switch must be off.
- Do not exchange the DCM (telematics transceiver) with one from another vehicle.

NEXT  **PERFORM DCM ACTIVATION**

