

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000028X1L
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: BRAKE CONTROL / DYNAMIC CONTROL SYSTEMS: ELECTRONICALLY CONTROLLED BRAKE SYSTEM: C052696; Steering Angle Sensor Module Component Internal Failure; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

DTC	C052696	Steering Angle Sensor Module Component Internal Failure
------------	----------------	--

DESCRIPTION

The No. 2 skid control ECU (brake actuator assembly) outputs this DTC when it receives an internal malfunction signal from the steering angle sensor.

DTC NO.	DETECTION ITEM	DTC DETECTION CONDITION	TROUBLE AREA	MIL	DTC OUTPUT FROM	PRIORITY	NOTE
C052696	Steering Angle Sensor Module Component Internal Failure	With the +BS terminal voltage 9.5 to 17.4 V, the No. 2 skid control ECU (brake actuator assembly) receives an error signal from the steering angle sensor.	Steering angle sensor	Does not come on	Brake/EPB	A	Output ECU: No. 2 skid control ECU (brake actuator assembly)

PROCEDURE

1.	REPLACE STEERING ANGLE SENSOR
-----------	--------------------------------------

HINT:

[Click here](#) 

NEXT  **END**

