VSA Modulator-Control Unit Update

Procedure

NOTE:

- To ensure the latest program is installed, do a VSA modulator-control unit update whenever the VSA modulator-control unit is replaced.
- High temperature in the engine compartment might cause the VSA modulator-control unit to become too hot to run the update. If the engine has been running before this procedure, open the hood and cool the engine compartment.

1. VSA Modulator-Control Unit - Update

2. VSA Sensor Neutral Position - Memorize

3. TPMS - Calibrate