

The symbols in the mass production body welding diagrams and in the replacement illustrations carry the following meanings:

(Mass Production Body Welding Diagram)

\* : Spot welding

▽ : MIG welding

X : 2-plate welding

⊗ : 3-plate welding

⊠ : 4-plate welding

P= : Spot welding pitch

L= : MIG welding length

Unit: mm (in.)

( ) : The number of spot welds.

(Replacement Illustration)

X : Spot welding

● : MIG welding

NOTE: The welding symbols in the illustrations don't show exact welding locations. For exact welding locations, refer to the mass production body welding diagrams.