

Removal

- Remove the rear panel, and check the rear panel side stiffener for damage. If necessary, replace the rear panel side stiffener.
- Drill the spot welds (Ⓐ position) of the rear fender upper extension.

