Refinishing Processes

Paint damage can appear in any form. Before making a repair, check the damaged area carefully, and determine the best procedure for repairing the damage. The following shows you refinishing methods for various types of paint damage or defects.

Processes	Procedures	Damage			Replacement Parts	
		To metal surface	To undercoat / intermediate coats	To top coat	Welded part	Single part
1. Preprocessing of Painting	 Featheredging Preparation of metal surface Air blowing / degreasing 	Å			†	
2. Treatment of Metal Surface	 Filling / drying Polishing Air blowing / degreasing 	☆				
3. Undercoating	 Masking Spraying primer surfacer Drying Polishing Air blowing / degreasing 					
4. Intermediate Coating	 Masking Spraying top coat enamel Drying Polishing Air blowing / degreasing 					A
5. Top Coating	 Masking Spraying top coat enamel / clear coat Drying Polishing / buffing 					

 ${\bf k}$: Indicates the best method depending on the degree of damage.