




Connector Views

91. Motor Current Sensor

- Gray
- Left side of PCU
- On power converter wire harness



U Phase:

- 1 GRN/BLK (IMA system)
- 2 BLU/ORN (IMA system)
- 3 WHT (IMA system)

V Phase:

- 1 YEL/BLU (IMA system)
- 2 GRY (IMA system)
- 3 RED/BLU (IMA system)

W Phase:

- 1 YEL (IMA system)
- 2 BRN (IMA system)
- 3 GRN (IMA system)