

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000029X7Q
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: NETWORKING: CXPI COMMUNICATION SYSTEM: PRECAUTION; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

PRECAUTION

PRECAUTION FOR POWER DISTRIBUTION BOX ASSEMBLY

- (a) Do not remove or install the power distribution box assembly with the negative (-) auxiliary battery terminal connected.

NOTICE:

After the ignition switch is turned off, there may be a waiting time before disconnecting the negative (-) auxiliary battery terminal.

Click here [INFO](#)

HINT:

When disconnecting and reconnecting the auxiliary battery, there is an automatic learning function that completes learning when the respective system is used.

Click here [INFO](#)

- (b) Make sure that the power distribution box assembly is not exposed to water, as it is not waterproof.
- (c) Some loads are connected to circuits with dedicated overcurrent protection. Therefore, do not use parts other than those specified for the vehicle.
- (d) When replacing the power distribution box assembly, the system may not operate normally if the same part number is not used.
- (e) Check that systems are operating normally before proceeding with troubleshooting.

