

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000028NQI
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: TIRE PRESSURE MONITORING: TIRE PRESSURE WARNING SYSTEM: PROBLEM SYMPTOMS TABLE; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

PROBLEM SYMPTOMS TABLE

HINT:

- Use the table below to help determine the cause of problem symptoms. If multiple suspected areas are listed, the potential causes of the symptoms are listed in order of probability in the "Suspected Area" column of the table. Check each symptom by checking the suspected areas in the order they are listed. Replace parts as necessary.
- Inspect the fuses and relays related to this system before inspecting the suspected areas below.

Tire Pressure Warning System

SYMPTOM	SUSPECTED AREA	LINK
Tire pressure warning light does not illuminate despite tire pressure decreasing	Initialization	INFO
	Check Data List (ID Tire Inflation Pressure)	INFO
	ID code check (Registration)	INFO
	Tire pressure warning light circuit	INFO
Tire pressure warning light remains illuminated (Goes off during initial check)	Tire pressure warning light circuit	INFO
Tire pressure warning light remains illuminated (Illuminates during initial check)	Check Data List (ID Tire Inflation Pressure)	INFO
	Tire pressure adjustment	INFO
	ID code check (Registration)	INFO
	Initialization	INFO
Initialization cannot be done	Tire pressure warning reset switch (steering pad switch assembly)	INFO
Tire position not identified	Refer to "Tire Position Not Identified".	INFO
Cannot enter to automatic ID registration mode	Tire pressure warning reset switch (steering pad switch assembly)	INFO

