

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM10000000293TW
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: HORN: HORN: INSPECTION; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

INSPECTION

PROCEDURE

1. INSPECT LOW PITCHED HORN ASSEMBLY

(a) Apply auxiliary battery voltage and check the operation of the low pitched horn assembly according to the table below.

OK:




[Click Location & Routing\(A22\)](#)

[Click Connector\(A22\)](#)

TESTER CONNECTION	SPECIFIED CONDITION
A22-1 - Auxiliary battery positive (+) Body ground - Auxiliary battery negative (-)	Horn sounds

If the result is not as specified, replace the low pitched horn assembly.



*a	Component without harness connected (Low Pitched Horn Assembly)
*b	Body Ground

