


Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM10000000292L3
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: LIGHTING (EXT): HAZARD WARNING SWITCH: REMOVAL; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

REMOVAL


CAUTION / NOTICE / HINT

COMPONENTS (REMOVAL)



	PROCEDURE	PART NAME CODE			
1	FRONT DOOR SCUFF PLATE LH	67914	-	-	-
2	COWL SIDE TRIM BOARD LH	62112	-	-	-
3	NO. 1 INSTRUMENT PANEL UNDER COVER SUB-ASSEMBLY	55606	-	-	-

*A	w/ Knee Airbag	-	-
----	----------------	---	---



PROCEDURE	PART NAME CODE			
4 LOWER CENTER INSTRUMENT PANEL FINISH PANEL	55434B	-	-	-
5 LOWER CENTER INSTRUMENT CLUSTER FINISH PANEL SUB-ASSEMBLY	55406B	-	-	-
6 FRONT DOOR OPENING TRIM WEATHERSTRIP	62311B	-	-	-
7 INSTRUMENT SIDE PANEL	55317A	-	-	-
8 NO. 2 INSTRUMENT PANEL GARNISH SUB-ASSEMBLY WITH AIR CONDITIONING CONTROL ASSEMBLY	-	-	-	-
9 CENTER INSTRUMENT CLUSTER FINISH PANEL ASSEMBLY	55420A	INFO	-	-
10 NO. 3 INSTRUMENT PANEL REGISTER ASSEMBLY	55670	-	-	-
11 HAZARD WARNING SIGNAL SWITCH ASSEMBLY	84330	-	-	-

PROCEDURE

1. REMOVE FRONT DOOR SCUFF PLATE LH (w/ Knee Airbag)

Click here [INFO](#)

2. REMOVE COWL SIDE TRIM BOARD LH (w/ Knee Airbag)

Click here [INFO](#)

3. REMOVE NO. 1 INSTRUMENT PANEL UNDER COVER SUB-ASSEMBLY (w/ Knee Airbag)

Click here [INFO](#)

4. REMOVE LOWER CENTER INSTRUMENT PANEL FINISH PANEL

Click here [INFO](#)

5. REMOVE LOWER CENTER INSTRUMENT CLUSTER FINISH PANEL SUB-ASSEMBLY

Click here [INFO](#)

6. DISCONNECT FRONT DOOR OPENING TRIM WEATHERSTRIP

Click here [INFO](#)

7. REMOVE INSTRUMENT SIDE PANEL

Click here [INFO](#)

8. REMOVE NO. 2 INSTRUMENT PANEL GARNISH SUB-ASSEMBLY WITH AIR CONDITIONING CONTROL ASSEMBLY

Click here [INFO](#)

9. REMOVE CENTER INSTRUMENT CLUSTER FINISH PANEL ASSEMBLY



Click here [INFO](#)

10. REMOVE NO. 3 INSTRUMENT PANEL REGISTER ASSEMBLY

Click here [INFO](#)

11. REMOVE HAZARD WARNING SIGNAL SWITCH ASSEMBLY

