Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000029X75		
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -	]	
Title: WINDOW / GLASS: WINDOW DEFOGGER SYSTEM: PROBLEM SYMPTOMS TABLE; 2023 - 2024 MY Prius Prius				
Prime [12/2022 - ]				

## **PROBLEM SYMPTOMS TABLE**

## **NOTICE:**

If the window defogger system is operated when the auxiliary battery voltage is low, due to the electrical load limit control that gives voltage supply priority to the power steering system, the window defogger system may not operate. In this case, check the vehicle control history (RoB) of the power steering system and check that "Battery Voltage Drop: X208F" is not stored before proceeding with troubleshooting.

Click here

## HINT:

Use the table below to help determine the cause of problem symptoms. If multiple suspected areas are listed, the potential causes of the symptoms are listed in order of probability in the "Suspected Area" column of the table. Check each symptom by checking the suspected areas in the order they are listed. Replace parts as necessary.

## Window Defogger System

SYMPTOM	SUSPECTED AREA	LINK
	Proceed to the "Rear Window Defogger System does not Operate"	INFO

.

TOYOTA