

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000002AQOD
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [03/2023 -]
Title: HEATING / AIR CONDITIONING: AIR CONDITIONING SYSTEM (for PHEV Model): VEHICLE CONTROL HISTORY (RoB); 2023 - 2024 MY Prius Prime [03/2023 -]		

VEHICLE CONTROL HISTORY (RoB)

CHECK VEHICLE CONTROL HISTORY

(a) Read the Vehicle Control History (RoB) according to the display on the GTS.

Body Electrical > Air Conditioner > Utility

TESTER DISPLAY
Vehicle Control History (RoB)

Vehicle Control History (RoB)

CODE	TESTER DISPLAY	MEASUREMENT ITEM	DIAGNOSTIC NOTE
X210F	Refrigerant Overabundance Filling History	Refrigerant was overfilled	Stop the compressor when excessive refrigerant charging is detected Detection Condition: <ul style="list-style-type: none"> A refrigerant temperature malfunction is detected during refrigerant charging mode

CLEAR VEHICLE CONTROL HISTORY

NOTICE:

When the vehicle control history (RoB) is cleared, all the stored history items are cleared.

(a) According to the display on the GTS, clear the Vehicle Control History (RoB).

Body Electrical > Air Conditioner > Utility

TESTER DISPLAY
Vehicle Control History (RoB)

