


Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000029ZVY
Model Year Start: 2023	Model: Prius	Prod Date Range: [12/2022 -]
Title: HEATING / AIR CONDITIONING: CONDENSER (for HEV Model): DISASSEMBLY; 2023 - 2024 MY Prius [12/2022 -]		

DISASSEMBLY

CAUTION / NOTICE / HINT

COMPONENTS (DISASSEMBLY)




PROCEDURE	PART NAME CODE	!	📄	⚙️
1 COOLER DRYER	88474	INFO	-	-

*1	CAP	-	-
•	Non-reusable part	-	-

PROCEDURE

1. REMOVE COOLER DRYER



*a	Modulator	-	-
----	-----------	---	---

- (1) Using a 14 mm straight hexagon, remove the cap from the modulator.
- (2) Using pliers, remove the cooler dryer from the modulator.

