

| | | |
|--|---------------------------|--------------------------------------|
| Last Modified: 12-04-2024 | 6.11:8.1.0 | Doc ID: RM100000029EKB |
| Model Year Start: 2023 | Model: Prius Prime | Prod Date Range: [12/2022 -] |
| Title: MY SETTINGS: MY SETTINGS SYSTEM: Driver Identification Method cannot be Set; 2023 - 2024 MY Prius Prius Prime [12/2022 -] | | |

Driver Identification Method cannot be Set

DESCRIPTION

When a setting assignment using the multi-display is performed, the smart key system (for Start Function) and audio and visual system will use the device when performing a search. If detected, settings can be assigned. If there is no detection, it is suspected that the radio and display receiver assembly or each system is malfunctioning.

CAUTION / NOTICE / HINT

NOTICE:

Before replacing the main body ECU (multiplex network body ECU), refer to Precaution.

Click here [INFO](#)

PROCEDURE

| | |
|-----------|---------------------------|
| 1. | CHECK THE SYMPTOMS |
|-----------|---------------------------|

(a) Check the problem symptoms.

| RESULT | PROCEED TO |
|---|------------|
| Assignment of settings cannot be performed using the electrical key transmitter sub-assembly. | A |
| Assignment of settings cannot be performed using the Bluetooth device. | B |

B  **GO TO STEP 4**

A



| | |
|-----------|--|
| 2. | CHECK SMART KEY SYSTEM (for Start Function) |
|-----------|--|

(a) Check the smart key system (for Start Function).

Click here [INFO](#)

OK:

Smart key system (for Start Function) is normal

NG ► **GO TO SMART KEY SYSTEM (for Start Function)****OK****3. CHECK MAIN BODY ECU (MULTIPLEX NETWORK BODY ECU)**

(a) Temporarily replace the main body ECU (multiplex network body ECU) with a new one.

Click here 

(b) Check if settings can be assigned again to an electrical key transmitter sub-assembly.

Click here 

OK:

All of the electrical key transmitter sub-assemblies could be registered to the new certification ECU (smart key ECU assembly) successfully.

OK ► **END (MAIN BODY ECU (MULTIPLEX NETWORK BODY ECU) WAS DEFECTIVE)****NG** ► **REPLACE RADIO AND DISPLAY RECEIVER ASSEMBLY****4. CHECK RECALL OPERATION (Assigned Settings Inspection)**

(a) Check if settings can be assigned again to an electrical key transmitter sub-assembly.

OK:

Settings can be assigned

OK ► **GO TO AUDIO AND VISUAL SYSTEM (PROBLEM SYMPTOMS TABLE)** **NG** ► **GO TO STEP 2**