

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000291Z3
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: AUDIO / VIDEO: AUDIO AND VISUAL SYSTEM: When Voice Recognition Switch is Pressed a Short Beep is Emitted but the Voice Recognition System does not Start; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

When Voice Recognition Switch is Pressed a Short Beep is Emitted but the Voice Recognition System does not Start

PROCEDURE

1. CHECK CONDITION

(a) While paying attention to the condition of the spoken voice command, perform a voice recognition operation.

OK:

Voice command is recognized normally.

HINT:

- When the voice command is recognized, the content of the voice command is displayed in the voice recognition result display area to the right of the mic icon.
- If an unnecessary word (such as "um" or "ah") is spoken before or after the recognition word, the system incorrectly recognizes the recognition word.
- The system cannot recognize voice commands when multiple people are speaking simultaneously.
- If the speaking speed is too fast or too slow, the recognition rate may decrease.
- The system may have difficulty recognizing voice commands depending on the voice quality (such as a hoarse voice due to poor physical condition).

OK ► **END (VOICE RECOGNITION MAY BE DIFFICULT DUE TO SPEECH CONDITION)**

NG ► **PROCEED TO NEXT SUSPECTED AREA SHOWN IN PROBLEM SYMPTOMS TABLE** 

