


Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000029TL8
Model Year Start: 2023	Model: Prius	Prod Date Range: [12/2022 -]
Title: MAINTENANCE: 2ZR-FXE SPARK PLUG: INSTALLATION; 2023 - 2024 MY Prius [12/2022 -]		


INSTALLATION

CAUTION / NOTICE / HINT

COMPONENTS (INSTALLATION)



	PROCEDURE	PART NAME CODE	!	📄	⚙️
1	SPARK PLUG	19100P	INFO	-	-
2	IGNITION COIL ASSEMBLY	19500	INFO	-	-
3	CENTER NO. 2 COWL TOP VENTILATOR LOUVER	55784B	-	-	-
4	PERFORM INITIALIZATION	-	-	-	INFO

	N*m (kgf*cm, ft.*lbf): Specified torque	-	-
---	---	---	---

PROCEDURE

1. INSTALL SPARK PLUG



NOTICE:

If a spark plug has been struck or dropped, replace it.

Torque:

20 N·m {204 kgf·cm, 15 ft·lbf}

2. INSTALL IGNITION COIL ASSEMBLY



Click here [INFO](#)

3. INSTALL CENTER NO. 2 COWL TOP VENTILATOR LOUVER

4. PERFORM INITIALIZATION

(a) Perform "Inspection After Repair" after replacing an ignition coil assembly or spark plug.

Click here [INFO](#)

