

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000029H5R
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: STEERING COLUMN: HEATED STEERING WHEEL SYSTEM: PRECAUTION; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

PRECAUTION

PRECAUTIONS FOR DISCONNECTING CABLE FROM NEGATIVE (-) AUXILIARY BATTERY TERMINAL

NOTICE:

After the ignition switch is turned off, there may be a waiting time before disconnecting the negative (-) auxiliary battery terminal.

Click here [INFO](#)

HINT:

When disconnecting and reconnecting the auxiliary battery, there is an automatic learning function that completes learning when the respective system is used.

Click here [INFO](#)

HANDLING PRECAUTIONS FOR SRS AIRBAG SYSTEM

CAUTION:

This vehicle is equipped with a Supplemental Restraint System (SRS). Failure to carry out service operations in the correct sequence could cause the SRS to unexpectedly deploy during servicing. This may cause a serious accident.

Before servicing (including inspection, replacement, removal and installation of parts), be sure to read the precautionary notices for Supplemental Restraint System.



Click here [INFO](#)

