

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000028BXH
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: HORN: HORN SYSTEM: PROBLEM SYMPTOMS TABLE; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

PROBLEM SYMPTOMS TABLE

NOTICE:

Before replacing the main body ECU (multiplex network body ECU), refer to Service Bulletin.

HINT:

Use the table below to help determine the cause of problem symptoms. If multiple suspected areas are listed, the potential causes of the symptoms are listed in order of probability in the "Suspected Area" column of the table. Check each symptom by checking the suspected areas in the order they are listed. Replace parts as necessary.

Horn System

SYMPTOM	SUSPECTED AREA	LINK
Horn does not sound	HORN fuse	-
	HORN relay	INFO
	Horn button assembly	INFO
	Spiral cable sub-assembly	INFO
	Power distribution box assembly	INFO
	Harness or connector	-
Horn sounds all the time	HORN relay	INFO
	Horn button assembly	INFO
	Spiral cable sub-assembly	INFO
	Power distribution box assembly	INFO
	Main body ECU (Multiplex network body ECU)	INFO
	Harness or connector	-

