

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000029H5V
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: STEERING COLUMN: HEATED STEERING WHEEL SYSTEM: PROBLEM SYMPTOMS TABLE; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

PROBLEM SYMPTOMS TABLE

Heated Steering Wheel System

SYMPTOM	SUSPECTED AREA	LINK
Steering wheel does not heat up when heated steering wheel switch is pressed	STRG HTR fuse	-
	ECU-IGP NO. 3 Fuse	-
	ECU-B NO. 3 Fuse	-
	Harness or connector	-
	CAN communication system	INFO
	Air conditioning system	INFO
	Meter / Gauge system	INFO
	Spiral cable sub-assembly	INFO
	Steering heater switch	INFO
	Refer to "Steering wheel does not heat up when heated steering wheel switch is pressed"	INFO

