

<b>Last Modified:</b> 12-04-2024	6.11:8.1.0	<b>Doc ID:</b> RM100000002924H
<b>Model Year Start:</b> 2023	<b>Model:</b> Prius Prime	<b>Prod Date Range:</b> [12/2022 - ]
<b>Title:</b> DOOR / HATCH: FUEL LID OPENER SYSTEM: PROBLEM SYMPTOMS TABLE; 2023 - 2024 MY Prius Prius Prime [12/2022 - ]		

## **PROBLEM SYMPTOMS TABLE**

**NOTICE:**

- When replacing the combination meter assembly, always replace it with a new one. If a combination meter assembly which was installed to another vehicle is used, the information stored in it will not match the information from the vehicle and a DTC may be stored.
- After replacing combination meter assembly, it may be necessary to update the ECU security key.

[Click here](#)

**HINT:**

- If a malfunction occurs in the close tank valve assembly or vapor pressure sensor, the fuel lid opener does not operate due to ECM control.
- If the fuel lid opener operates after a short time, the close tank valve assembly or fuel tank vent hose may be clogged.

**Fuel Lid Opener System (for M20A-FXS)**

SYMPTOM	SUSPECTED AREA	LINK
Fuel lid opener does not operate	Proceed to "Fuel Lid Opener does not Operate"	<a href="#">INFO</a>
Messages are not displayed on the multi-information display in the combination meter assembly	Harness or connector	-
	Combination meter assembly	<a href="#">INFO</a>
	ECM	<a href="#">INFO</a>

**Fuel Lid Opener System (for 2ZR-FXE)**

SYMPTOM	SUSPECTED AREA	LINK
Fuel lid opener does not operate	Proceed to "Fuel Lid Opener does not Operate"	<a href="#">INFO</a>

