

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000029X4F
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: SEAT: CLIMATE CONTROL SEAT SYSTEM: PROBLEM SYMPTOMS TABLE; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

PROBLEM SYMPTOMS TABLE

NOTICE:

If the climate control seat system is operated when the auxiliary battery voltage is low, due to the electrical load limit control that gives voltage supply priority to the power steering system, the climate control seat system may not operate. In this case, check the vehicle control history (RoB) of the power steering system and check that "Battery Voltage Drop: X208F" is not stored before proceeding with troubleshooting.

Click here [INFO](#)

HINT:

- Use the table below to help determine the cause of problem symptoms. If multiple suspected areas are listed, the potential causes of the symptoms are listed in order of probability in the "Suspected Area" column of the table. Check each symptom by checking the suspected areas in the order they are listed. Replace parts as necessary.
- Inspect the fuses and relays related to this system before inspecting the suspected areas below.

Climate Control Seat System

SYMPTOM	SUSPECTED AREA	LINK
Seat blower volume is low (for Driver Seat)	Seat cushion climate control blower assembly LH	INFO
	Seatback climate control blower LH	INFO
Seat blower volume is low (for Front Passenger Seat)	Seat cushion climate control blower assembly RH	INFO
	Seatback climate control blower RH (lumbar support adjuster assembly RH)	INFO
Seat blower volume does not change (for Driver Seat)	Air conditioning control assembly	INFO
	Seat cushion climate control blower assembly LH	INFO
	Seatback climate control blower LH	INFO
	Air conditioning amplifier assembly	INFO
Seat blower volume does not change (for Front Passenger Seat)	Air conditioning control assembly	INFO
	Seat cushion climate control blower assembly RH	INFO

SYMPTOM	SUSPECTED AREA	LINK
	Seatback climate control blower RH (lumbar support adjuster assembly RH)	INFO
	Air conditioning amplifier assembly	INFO
Both driver side seat blower and front passenger side seat blower do not operate	Air conditioning control assembly	INFO
	Air conditioning amplifier assembly	INFO
	Power distribution box assembly	INFO
	Wire harness or connector	-
Climate control seat system does not operate (for Driver Seat)	Refer to the "Climate Control Seat System does not Operate on Driver Side".	INFO
Climate control seat system does not operate (for Front Passenger Seat)	Refer to the "Climate Control Seat System does not Operate on Passenger Side".	INFO

