


Connector Views

130. Motor Commutation Sensor

- Gray
- Middle rear of engine
- On engine wire harness



- | | |
|---|---|
| 1 GRN (CMB output) | 6 — |
| 2 Male – BLU Female – WHT (CMA output) | 7 PNK (Sensor voltage (VCC3)) |
| 3 Male – WHT Female – BRN (CMC output) | 8 Male – GRY Female – BLU (Sensor ground) |
| 4 YEL (Sensor voltage (VCC2)) | 9 Male – BLK Female – RED (Sensor ground) |
| 5 Male – PNK Female – ORN (Sensor voltage (VCC1)) | 10 Male – BLK Female – LT GRN (Sensor ground) |