12/9/24, 3:09 PM

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000289LP		
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]	
Title: ADVANCED DRIVER ASSISTANCE SYSTEM: FRONT CAMERA SYSTEM: PROBLEM SYMPTOMS TABLE; 2023 -				
2024 MY Prius Prius Prime [12/2022 -]				

PROBLEM SYMPTOMS TABLE

HINT:

- If no DTC is output when a diagnosis code check is performed for the front camera system and the CAN communication system, perform diagnosis according to the following symptoms.
- Use the table below to help determine the cause of problem symptoms. If multiple suspected areas are listed, the potential causes of the symptoms are listed in order of probability in the "Suspected Area" column of the table. Check each symptom by checking the suspected areas in the order they are listed. Replace parts as necessary.
- Inspect the fuses and relays related to this system before inspecting the suspected areas below.

Front Camera System

SYMPTOM	SUSPECTED AREA	LINK
Driving assist switch, +RES switch, - switch, CANCEL switch cannot be operated	Steering pad switch circuit	INFO
	Hybrid vehicle control ECU	INFO
Driving assist mode select switch cannot be operated	Steering pad switch circuit	INFO
Vehicle-to-vehicle distance switch cannot be operated	Steering pad switch circuit	INFO
LTA switch cannot be operated	Steering pad switch circuit	INFO

•

ΤΟΥΟΤΑ