

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM10000000294WO
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: AUDIO / VIDEO: PILLAR SPEAKER: INSPECTION; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

INSPECTION

PROCEDURE

1. INSPECT FRONT NO. 2 SPEAKER ASSEMBLY

- (a) With the speaker installed, check that there is no looseness or other abnormalities.
- (b) Check that there is no foreign matter in the speaker, no tears on the speaker cone or other abnormalities.
- (c) When there is a possibility that either the right or left speaker is malfunctioning, interchange the speakers and perform an inspection. If the malfunction disappears after interchanging the speakers, replace the malfunctioning speaker.

HINT:

Connect all connectors to the speakers when performing an inspection. If the result is not as specified, replace the speaker.

