

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM10000002C0DT
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [03/2023 -]
Title: PARK ASSIST / MONITORING: BLIND SPOT MONITOR SYSTEM: DIAGNOSTIC TROUBLE CODE CHART; 2023 - 2024 MY Prius Prius Prime [03/2023 -]		

DIAGNOSTIC TROUBLE CODE CHART

Blind Spot Monitor System

DTC NO.	DETECTION ITEM	DTC OUTPUT FROM	PRIORITY	LINK
C1AB411	Outer Mirror Indicator (Module "B" Side) Circuit Short to Ground	Blind Spot Monitor "B"	A	INFO
C1AB412	Outer Mirror Indicator (Module "B" Side) Circuit Short to Battery	Blind Spot Monitor "B"	A	INFO
C1AB413	Outer Mirror Indicator (Module "B" Side) Circuit Open	Blind Spot Monitor "B"	A	INFO
C1AB511	Outer Mirror Indicator (Module "A" Side) Circuit Short to Ground	Blind Spot Monitor "A"	A	INFO
C1AB512	Outer Mirror Indicator (Module "A" Side) Circuit Short to Battery	Blind Spot Monitor "A"	A	INFO
C1AB513	Outer Mirror Indicator (Module "A" Side) Circuit Open	Blind Spot Monitor "A"	A	INFO
C1AB604	Rear Side Radar Sensor (Module "B") System Internal Failure	Blind Spot Monitor "B"	A	INFO
C1AB704	Rear Side Radar Sensor (Module "A") System Internal Failure	Blind Spot Monitor "A"	A	INFO
C1AC100	Rear Side Radar Sensor (Module "B") Beam Axis Misalignment (Horizontal)	Blind Spot Monitor "B"	A	INFO
C1AC200	Rear Side Radar Sensor (Module "A") Beam Axis Misalignment (Horizontal)	Blind Spot Monitor "A"	A	INFO
U012987	Lost Communication with Brake System Control Module "A" Missing Message	Blind Spot Monitor "B"	B	INFO

DTC NO.	DETECTION ITEM	DTC OUTPUT FROM	PRIORITY	LINK
U013187	Lost Communication with Power Steering Control Module Missing Message	Blind Spot Monitor "B"	B	INFO
U014087	Lost Communication with Body Control Module Missing Message	Blind Spot Monitor "B"	B	INFO
U016387	Lost Communication with Navigation Control Module Missing Message	Blind Spot Monitor "B"	B	INFO
U023287	Lost Communication with Side Obstacle Detection Control Module "A" Missing Message	Blind Spot Monitor "B"	A	INFO
U023387	Lost Communication with Side Obstacle Detection Control Module "B" Missing Message	Blind Spot Monitor "A"	A	INFO
U029387	Lost Communication with Hybrid/EV Powertrain Control Module Missing Message	Blind Spot Monitor "B"	B	INFO
U032251	Software Incompatibility with Body Control Module Not Programmed	Blind Spot Monitor "B"	A	INFO
U032251	Software Incompatibility with Body Control Module Not Programmed	Blind Spot Monitor "A"	A	INFO
U032257	Software Incompatibility with Body Control Module Invalid/Incompatible Software Component	Blind Spot Monitor "B"	A	INFO
U032257	Software Incompatibility with Body Control Module Invalid/Incompatible Software Component	Blind Spot Monitor "A"	A	INFO
U114F87	Lost Communication with Power Integration Module Missing Message	Blind Spot Monitor "B"	B	INFO

