

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000029185
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: PARK ASSIST / MONITORING: PANORAMIC VIEW MONITOR SYSTEM: C161404,C161B04; Circumference Monitoring Camera Control Module System Internal Failure; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

DTC	C161404	Circumference Monitoring Camera Control Module System Internal Failure
------------	----------------	---

DTC	C161B04	Rear Camera Control Module System Internal Failure
------------	----------------	---

DESCRIPTION

This DTC is stored if the parking assist ECU judges that there is an internal malfunction as a result of its self check.

DTC NO.	DETECTION ITEM	DTC DETECTION CONDITION	TROUBLE AREA	DTC OUTPUT FROM	PRIORITY
C161404	Circumference Monitoring Camera Control Module System Internal Failure	ECU internal malfunction	Parking assist ECU	Circumference Monitoring Camera Control Module	A
C161B04	Rear Camera Control Module System Internal Failure	ECU internal malfunction	Parking assist ECU	Circumference Monitoring Camera Control Module	A

CAUTION / NOTICE / HINT

NOTICE:

Depending on the parts that are replaced or operations that are performed during vehicle inspection or maintenance, calibration of other systems as well as the panoramic view monitor system may be needed.

Click here [INFO](#)

PROCEDURE

1.	CHECK CAMERA IMAGE OR CHECK FOR DTCS
-----------	---

(a) Check the image of the cameras or check for DTCs, and proceed to the respective link below.

RESULT	PROCEED TO
DTC C162287, C168187, C168E87, or C169D87 is output	A
The image of the front, rear, right side, or left side camera is black	B
DTC C162287, C168187, C168E87, and C169D87 are not output	C

A ▶ **PROCEED TO THE RESPECTIVE PROCEDURE**

B ▶ **PROCEED TO THE RESPECTIVE PROCEDURE**

C



2.	REPLACE PARKING ASSIST ECU
-----------	-----------------------------------

(a) Replace the parking assist ECU with a new one.

HINT:

Click here 

NEXT ▶ **END**

