

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM10000000292G8
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: M20A-FXS (INTAKE / EXHAUST): INTAKE SYSTEM: ON-VEHICLE INSPECTION; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

ON-VEHICLE INSPECTION

CAUTION / NOTICE / HINT

The necessary procedures (adjustment, calibration, initialization or registration) that must be performed after parts are removed and installed, or replaced when repairing air leaks in the intake system are shown below.

Necessary Procedures After Parts Removed/Installed/Replaced


REPLACED PART OR PERFORMED PROCEDURE	NECESSARY PROCEDURE	EFFECT/INOPERATIVE FUNCTION WHEN NECESSARY PROCEDURE NOT PERFORMED	LINK
Air leak from intake system is repaired	Inspection After Repair	<ul style="list-style-type: none"> • Poor idle, etc. • Engine start function, etc. 	INFO

PROCEDURE

1. INSPECT INTAKE SYSTEM

CAUTION:

To prevent injury due to contact with an operating cooling fan, keep your hands and clothing away from the cooling fans when working in the engine compartment with the engine running or the power switch on (IG).




HINT:

Perform "Inspection After Repair" after repairing vacuum leaks in the intake system.

Click here [INFO](#)

(a) Check that there are no vacuum leaks at the points shown in the illustration.



2. PERFORM INITIALIZATION

(a) Perform Inspection After Repair after repairing vacuum leaks in the intake system.

HINT:

[Click here](#) **INFO**

