


Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000028XBH
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: M20A-FXS (STARTING): POWER SWITCH: REMOVAL; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		




REMOVAL

CAUTION / NOTICE / HINT

COMPONENTS (REMOVAL)



PROCEDURE		PART NAME CODE			
1	LOWER CENTER INSTRUMENT PANEL FINISH PANEL	55434B	-	-	-
2	LOWER CENTER INSTRUMENT CLUSTER FINISH PANEL SUB-ASSEMBLY	55406B	-	-	-
3	FRONT DOOR OPENING TRIM WEATHERSTRIP RH	62311B	-	-	-
4	INSTRUMENT SIDE PANEL	55317A	-	-	-
5	NO. 2 INSTRUMENT PANEL GARNISH SUB-ASSEMBLY WITH AIR CONDITIONING CONTROL ASSEMBLY	-	-	-	-

PROCEDURE		PART NAME CODE			
6	CENTER INSTRUMENT CLUSTER FINISH PANEL ASSEMBLY	55420A	INFO	-	-
7	NO. 3 INSTRUMENT PANEL REGISTER ASSEMBLY	55670	-	-	-
8	POWER SWITCH	89611	-	-	-

PROCEDURE

1. REMOVE LOWER CENTER INSTRUMENT PANEL FINISH PANEL

Click here [INFO](#)

2. REMOVE LOWER CENTER INSTRUMENT CLUSTER FINISH PANEL SUB-ASSEMBLY

Click here [INFO](#)

3. DISCONNECT FRONT DOOR OPENING TRIM WEATHERSTRIP RH

Click here [INFO](#)


4. REMOVE INSTRUMENT SIDE PANEL RH

Click here [INFO](#)

5. REMOVE NO. 2 INSTRUMENT PANEL GARNISH SUB-ASSEMBLY WITH AIR CONDITIONING CONTROL ASSEMBLY

Click here [INFO](#)

6. REMOVE CENTER INSTRUMENT CLUSTER FINISH PANEL ASSEMBLY

	Click here INFO
---	---------------------------------

7. REMOVE NO. 3 INSTRUMENT PANEL REGISTER ASSEMBLY

Click here [INFO](#)

8. REMOVE POWER SWITCH

