12/16/24, 7:42 PM

HYBRID / BATTERY CONTROL: HYBRID CONTROL SYSTEM (for PHEV Model): P1F689F; Motor Inverter Shutdown Performan...

Last Modified: 12-04-2024	6.11:8.1.0 Doc ID: RM10000002BI13							
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [03/2023 -]						
Title: HYBRID / BATTERY CONTROL: HYBRID CONTROL SYSTEM (for PHEV Model): P1F689F; Motor Inverter								
Shutdown Performance Stuck Off; 2023 - 2024 MY Prius Prime [03/2023 -]								

DTC

P1F689F Mo

Motor Inverter Shutdown Performance Stuck Off

DESCRIPTION

The hybrid vehicle control ECU detects malfunctions which prevent the generator (MG1) inverter and motor (MG2) inverter shutdown circuit from shutting down the hybrid vehicle control system.

DTC	DETECTION ITEM	DTC DETECTION	TROUBLE	MIL	WARNING	DTC	PRIORITY	NOTE
NO.		CONDITION	AREA		INDICATE	OUTPUT		
						FROM		
P1F689F	Motor Inverter Shutdown	Motor generator control ECU internal malfunction (1 trip detection logic)	Inverter with converter	Does not come on	Master Warning: Comes on	Hybrid Control		SAE Code: P1F68

CONFIRMATION DRIVING PATTERN

HINT:

After repair has been completed, clear the DTC and then check that the vehicle has returned to normal by performing the following All Readiness check procedure.

Click here

- 1. Clear the DTCs (even if no DTCs are stored, perform the clear DTC procedure).
- 2. Turn the ignition switch off and wait for 2 minutes or more.
- 3. Turn the ignition switch to ON (READY) and wait for 30 seconds or more.
- 4. Turn the ignition switch off and wait for 2 minutes or more.
- 5. Enter the following menus: Powertrain / Hybrid Control / Utility / All Readiness.
- 6. Check the DTC judgment result.

HINT:

- If the judgment result shows NORMAL, the system is normal.
- If the judgment result shows ABNORMAL, the system has a malfunction.
- If the judgment result shows INCOMPLETE, perform driving pattern again.

PROCEDURE

1. REPLACE INVERTER WITH CONVERTER ASSEMBLY

HINT:

Click here





