


Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000029P7V
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: MAINTENANCE: BATTERY COOLING FILTER: INSTALLATION; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

INSTALLATION

CAUTION / NOTICE / HINT

COMPONENTS (INSTALLATION)



PROCEDURE		PART NAME CODE	!	📄	⚙️
1	NO. 1 HV BATTERY INTAKE FILTER	G92DH	-	-	-
2	REAR UNDER SIDE COVER LH	76974E	-	-	-
3	CLEAR DTC	-	-	-	INFO

PROCEDURE

- 1. INSTALL NO. 1 HV BATTERY INTAKE FILTER**
- 2. INSTALL REAR UNDER SIDE COVER LH**
- 3. CLEAR DTC**



HINT:

If the message "Maintenance Required for Traction Battery Cooling Parts See Owner's Manual" is displayed on the multi-information display, clean or replace the No. 1 HV battery intake filter, and clear the DTCs to reset the learning values even if no DTCs are output.

for M20A-FXS: Click here [INFO](#)

for 2ZR-FXE: Click here [INFO](#)

