


Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000029P7T
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: MAINTENANCE: BATTERY COOLING FILTER: REMOVAL; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

REMOVAL

CAUTION / NOTICE / HINT


COMPONENTS (REMOVAL)



PROCEDURE		PART NAME CODE			
1	REAR UNDER SIDE COVER LH	76974E	-	-	-
2	NO. 1 HV BATTERY INTAKE FILTER	G92DH	INFO	-	-

PROCEDURE

1. REMOVE REAR UNDER SIDE COVER LH



2. REMOVE NO. 1 HV BATTERY INTAKE FILTER

	HINT:
If the message "Maintenance Required for Traction Battery Cooling Parts See Owner's Manual" is displayed on the multi-information display, inspect the No. 1 HV battery intake filter.	
Click here INFO	

