

| | | |
|---|---------------------------|--------------------------------------|
| Last Modified: 12-04-2024 | 6.11:8.1.0 | Doc ID: RM100000029PIG |
| Model Year Start: 2023 | Model: Prius Prime | Prod Date Range: [12/2022 -] |
| Title: MAINTENANCE: FRONT LOWER BALL JOINT: ON-VEHICLE INSPECTION; 2023 - 2024 MY Prius Prius Prime [12/2022 -] | | |

ON-VEHICLE INSPECTION

PROCEDURE

1. INSPECT FRONT LOWER BALL JOINT ASSEMBLY

(a) Check for looseness.

(1) Lift up the vehicle.

(2) Move the front lower No. 1 suspension arm sub-assembly up and down by hand with a force of 294 N (30 kgf) or more to check that there is no looseness at the front lower ball joint assembly.

HINT:

If the front lower ball joint assembly is loose, replace it with a new one.

