

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000028BWK
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: ACOUSTIC VEHICLE ALERTING SYSTEM: ACOUSTIC VEHICLE ALERTING SYSTEM: PRECAUTION; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

PRECAUTION

PRECAUTIONS FOR DISCONNECTING AND RECONNECTING CABLE TO NEGATIVE (-) AUXILIARY BATTERY TERMINAL

NOTICE:

- After the ignition switch is turned off, there may be a waiting time before disconnecting the negative (-) auxiliary battery terminal.

[Click here](#) 

HINT:

When disconnecting and reconnecting the auxiliary battery, there is an automatic learning function that completes learning when the respective system is used.

[Click here](#) 

PRECAUTIONS FOR ACOUSTIC VEHICLE ALERTING SYSTEM

(a) In the following cases, the volume or tone of the sound might change:

- (1) If the vehicle is parked in a very hot or cold environment for an extended period of time (function will return to normal after time passes)
- (2) If high pressure water is applied directly to the speaker from the bottom of the vehicle
- (3) If the front of the speaker is blocked by mud, snow, ice, etc.
- (4) If the entire speaker freezes

(b) In the following cases, it may be difficult to hear the sound from the speaker:

- (1) If the environment around the vehicle is very noisy (in a busy intersection or when an emergency vehicle is approaching)
- (2) If the listener is behind the vehicle. (Compared to a situation such as when a pedestrian is in front of the vehicle, the sound volume will seem to be lower when the car is reversing. This occurs because the speaker is installed facing the front of the vehicle.)

