

<b>Last Modified:</b> 12-04-2024	6.11:8.1.0	<b>Doc ID:</b> RM100000002B778
<b>Model Year Start:</b> 2023	<b>Model:</b> Prius Prime	<b>Prod Date Range:</b> [03/2023 - ]
<b>Title:</b> DOOR / HATCH: CHARGE LID OPENER SYSTEM: PRECAUTION; 2023 - 2024 MY Prius Prius Prime [03/2023 - ]		

## PRECAUTION

### PRECAUTIONS FOR DISCONNECTING CABLE FROM NEGATIVE (-) AUXILIARY BATTERY TERMINAL

#### NOTICE:

After the ignition switch is turned off, there may be a waiting time before disconnecting the negative (-) auxiliary battery terminal.

Click here [INFO](#)

#### HINT:

When disconnecting and reconnecting the auxiliary battery, there is an automatic learning function that completes learning when the respective system is used.

Click here [INFO](#)

### PRECAUTIONS FOR INSPECTING CHARGE LID OPENER SYSTEM

(a) Refer to the precaution of plug-in charge control system when inspecting the charge lid opener system.

Click here [INFO](#)

