


<b>Last Modified:</b> 12-04-2024	6.11:8.1.0	<b>Doc ID:</b> RM100000002925J
<b>Model Year Start:</b> 2023	<b>Model:</b> Prius Prime	<b>Prod Date Range:</b> [12/2022 - ]
<b>Title:</b> DOOR / HATCH: RESERVE LOCK SWITCH: REMOVAL; 2023 - 2024 MY Prius Prius Prime [12/2022 - ]		

## REMOVAL

### CAUTION / NOTICE / HINT

#### COMPONENTS (REMOVAL)




PROCEDURE		PART NAME CODE			
1	GLIDE DOOR INSIDE HANDLE BASE ASSEMBLY	69290G	<a href="#">INFO</a>	-	-
2	BACK DOOR CONTROL SWITCH	84931C	-	-	-


# PROCEDURE

## 1. REMOVE GLIDE DOOR INSIDE HANDLE BASE ASSEMBLY

	Click here <a href="#">INFO</a>
---	---------------------------------

## 2. REMOVE BACK DOOR CONTROL SWITCH



	Remove in this Direction	-	-
---	--------------------------	---	---

