


Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM10000002BYRW
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [03/2023 -]
Title: THEFT DETERRENT / KEYLESS ENTRY: ELECTRICAL KEY OSCILLATOR (for Rear Floor): REMOVAL; 2023 - 2024 MY Prius Prime [03/2023 -]		

REMOVAL

CAUTION / NOTICE / HINT

COMPONENTS (REMOVAL)



PROCEDURE		PART NAME CODE			
1	DECK BOARD ASSEMBLY	58410B	-	-	-
2	DECK FLOOR BOX RH	64995	-	-	-
3	DECK FLOOR BOX LH	64997	-	-	-
4	NO. 2 INDOOR ELECTRICAL KEY ANTENNA ASSEMBLY	899A0A	INFO	-	-

*A	w/ Spare Tire	*B	w/o Spare Tire
----	---------------	----	----------------

*C	for Type A	*D	for Type B
*a	HINT: As the illustration shown is an example, the actual details may differ.	-	-

PROCEDURE

1. REMOVE DECK BOARD ASSEMBLY

Click here [INFO](#)

2. REMOVE DECK FLOOR BOX RH

Click here [INFO](#)

3. REMOVE DECK FLOOR BOX LH

Click here [INFO](#)

4. REMOVE NO. 2 INDOOR ELECTRICAL KEY ANTENNA ASSEMBLY



NOTICE:

Be careful when removing the No. 2 indoor electrical key antenna assembly. If the No. 2 indoor electrical key antenna assembly is dropped, replace it with a new one.

