


Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM10000002AXEW
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [03/2023 -]
Title: HEATING / AIR CONDITIONING: AIR CONDITIONING AMPLIFIER: REMOVAL; 2023 - 2024 MY Prius Prius Prime [03/2023 -]		

REMOVAL

CAUTION / NOTICE / HINT


COMPONENTS (REMOVAL)



PROCEDURE		PART NAME CODE			
1	AIR CONDITIONING AMPLIFIER ASSEMBLY	88650N	-	-	-


PROCEDURE

1. REMOVE AIR CONDITIONING AMPLIFIER ASSEMBLY



	Remove in this Direction	-	-
--	--------------------------	---	---

(b) for HEV Model:



*A	w/o Seat Heater System	*B	w/ Seat Heater System
----	------------------------	----	-----------------------

(c) for PHEV Model:

