

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000029ZW0
Model Year Start: 2023	Model: Prius	Prod Date Range: [12/2022 -]
Title: HEATING / AIR CONDITIONING: CONDENSER (for HEV Model): ON-VEHICLE INSPECTION; 2023 - 2024 MY Prius [12/2022 -]		

ON-VEHICLE INSPECTION

PROCEDURE

1. INSPECT COOLER CONDENSER ASSEMBLY

- (a) If the cooler condenser assembly fins are dirty, clean them with water and dry them with compressed air.

NOTICE:

Do not damage the cooler condenser assembly fins.

- (b) If any cooler condenser assembly fins are bent, straighten them using a screwdriver or pliers.

2. INSPECT FOR REFRIGERANT LEAK

- (a) Using a gas leak detector, check the pipe joints for refrigerant leaks.
- (b) If a refrigerant leak is detected in a joint, check the torque of the joint.

