

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM10000002AXDB
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [03/2023 -]
Title: HEATING / AIR CONDITIONING: CONDENSER (for PHEV Model): ON-VEHICLE INSPECTION; 2023 - 2024 MY Prius Prime [03/2023 -]		

ON-VEHICLE INSPECTION

PROCEDURE

1. INSPECT COOLER CONDENSER ASSEMBLY

(a) If the cooler condenser assembly fins are dirty, clean them with water and dry them with compressed air.

NOTICE:

Do not damage the cooler condenser assembly fins.

(b) If any cooler condenser assembly fins are bent, straighten them using a screwdriver or pliers.

2. INSPECT FOR REFRIGERANT LEAK

(a) Using a gas leak detector, check the pipe joints for refrigerant leaks.

(b) If a refrigerant leak is detected in a joint, check the torque of the joint.

