

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM10000000294WP
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: AUDIO / VIDEO: PILLAR SPEAKER: REMOVAL; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

REMOVAL


CAUTION / NOTICE / HINT

HINT:

- Use the same procedure for the RH side and LH side.
- The following procedure is for the LH side.

CAUTION / NOTICE / HINT

COMPONENTS (REMOVAL)



	PROCEDURE	PART NAME CODE			
1	FRONT DOOR OPENING TRIM WEATHERSTRIP	62312B	-	-	-
2	FRONT PILLAR GARNISH LH	62212	INFO	-	-
3	FRONT NO. 2 SPEAKER ASSEMBLY	86160P	-	-	-

•	Non-reusable part	-	-
---	-------------------	---	---

PROCEDURE

1. DISCONNECT FRONT DOOR OPENING TRIM WEATHERSTRIP

Click here [INFO](#)

2. REMOVE FRONT PILLAR GARNISH LH

	Click here INFO
---	---------------------------------

3. REMOVE FRONT NO. 2 SPEAKER ASSEMBLY

