


Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000002A4CI
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: TIRE PRESSURE MONITORING: TIRE PRESSURE WARNING RECEIVER: INSTALLATION; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

INSTALLATION

CAUTION / NOTICE / HINT

COMPONENTS (INSTALLATION)



	PROCEDURE	PART NAME CODE			
1	TIRE PRESSURE WARNING ECU AND RECEIVER	897B0A	INFO	-	-
2	ROOF SIDE INNER GARNISH ASSEMBLY LH	62480A	-	-	-
3	PERFORM INITIALIZATION	-	-	-	INFO

	N*m (kgf*cm, ft.*lbf): Specified torque	-	-
--	---	---	---

PROCEDURE

1. INSTALL TIRE PRESSURE WARNING ECU AND RECEIVER

**NOTICE:**

- Do not drop the tire pressure warning ECU and receiver, strike it with tools or subject it to impact.
- If the tire pressure warning ECU and receiver is subjected to an impact, replace it with a new one.

Torque:**10 N·m {102 kgf·cm, 7 ft·lbf}****2. INSTALL ROOF SIDE INNER GARNISH ASSEMBLY LH**Click here [INFO](#)**3. PERFORM INITIALIZATION**Click here [INFO](#)**HINT:**

Refer to Procedures Necessary When Replacing Parts (for Tire Pressure Warning System).

