

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000028NQR
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: TIRE PRESSURE MONITORING: TIRE PRESSURE WARNING SYSTEM: U012987; Lost Communication With Brake System Control Module Missing Message; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

DTC	U012987	Lost Communication With Brake System Control Module Missing Message
------------	----------------	--

DESCRIPTION

The tire pressure warning ECU and receiver receives signals from the No. 2 skid control ECU (brake actuator assembly) via the CAN communication system.

DTC NO.	DETECTION ITEM	DTC DETECTION CONDITION	TROUBLE AREA	DTC OUTPUT FROM	PRIORITY
U012987	Lost Communication With Brake System Control Module Missing Message	Lost communication with No. 2 skid control ECU (brake actuator assembly)	<ul style="list-style-type: none"> CAN communication system No. 2 skid control ECU (brake actuator assembly) 	Tire Pressure Monitor	B

PROCEDURE

1.	GO TO CAN COMMUNICATION SYSTEM
-----------	---------------------------------------

(a) Go to CAN Communication System.

HINT:

Click here 

NEXT  **END**

