

Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000029X3U
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: SEAT: FRONT POWER SEAT CONTROL SYSTEM (w/o Memory): PROBLEM SYMPTOMS TABLE; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

PROBLEM SYMPTOMS TABLE

HINT:

- Use the table below to help determine the cause of problem symptoms. If multiple suspected areas are listed, the potential causes of the symptoms are listed in order of probability in the "Suspected Area" column of the table. Check each symptom by checking the suspected areas in the order they are listed. Replace parts as necessary.
- Inspect the fuses and relays related to this system before inspecting the suspected areas below.

Front Power Seat Control System (w/o Memory)

SYMPTOM	SUSPECTED AREA	LINK
All functions do not operate	Front power seat switch LH	INFO
	Wire harness or connector	-
Only slide function does not operate	Front power seat switch LH	INFO
	Slide motor (Upper seat track rail sub-assembly LH)	INFO
	Wire harness or connector	-
Only front vertical function does not operate	Front power seat switch LH	INFO
	Front vertical motor (Power seat tilt motor assembly LH)	INFO
	Wire harness or connector	-
Only lifter function does not operate	Front power seat switch LH	INFO
	Lifter motor (Power seat lifter motor assembly LH)	INFO
	Wire harness or connector	-
Only reclining function does not operate	Front power seat switch LH	INFO

SYMPTOM	SUSPECTED AREA	LINK
	Reclining motor (Front seatback frame sub-assembly LH)	INFO
	Wire harness or connector	-
Only lumbar support adjustment function does not operate	Front power seat switch LH	INFO
	Lumbar support adjuster assembly LH	INFO
	Wire harness or connector	-

