


Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM1000000290DE
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: THEFT DETERRENT / KEYLESS ENTRY: ELECTRICAL KEY OSCILLATOR (for Front Floor): REMOVAL; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		

REMOVAL

CAUTION / NOTICE / HINT

COMPONENTS (REMOVAL)



	PROCEDURE	PART NAME CODE			
1	REAR CONSOLE BOX ASSEMBLY	58910C	INFO	-	-
2	NO. 1 INDOOR ELECTRICAL KEY ANTENNA ASSEMBLY	899A0	INFO	-	-

PROCEDURE

1. REMOVE REAR CONSOLE BOX ASSEMBLY




Click here [INFO](#)

2. REMOVE NO. 1 INDOOR ELECTRICAL KEY ANTENNA ASSEMBLY



NOTICE:

Be careful when removing the No. 1 indoor electrical key antenna assembly. If the No. 1 indoor electrical key antenna assembly is dropped, replace it with a new one.



P

