


<b>Last Modified:</b> 12-04-2024	6.11:8.1.0	<b>Doc ID:</b> RM1000000289PM
<b>Model Year Start:</b> 2023	<b>Model:</b> Prius Prime	<b>Prod Date Range:</b> [12/2022 - ]
<b>Title:</b> ADVANCED DRIVER ASSISTANCE SYSTEM: AUTOMATIC HIGH BEAM MAIN SWITCH: REMOVAL; 2023 - 2024 MY Prius Prius Prime [12/2022 - ]		




## REMOVAL

### CAUTION / NOTICE / HINT

#### COMPONENTS (REMOVAL)



PROCEDURE		PART NAME CODE			
1	FRONT DOOR SCUFF PLATE LH	67914	-	-	-
2	COWL SIDE TRIM BOARD LH	62112	-	-	-

PROCEDURE		PART NAME CODE			
3	NO. 1 INSTRUMENT PANEL UNDER COVER SUB-ASSEMBLY	55606	-	-	-
4	LOWER CENTER INSTRUMENT PANEL FINISH PANEL	55434B	-	-	-
5	FRONT DOOR OPENING TRIM WEATHERSTRIP LH	62312B	-	-	-
6	INSTRUMENT SIDE PANEL LH	55318C	-	-	-
7	LOWER INSTRUMENT PANEL FINISH PANEL ASSEMBLY	55480D	-	-	-
8	INSTRUMENT CLUSTER FINISH PANEL ASSEMBLY	55410C	<a href="#">INFO</a>	-	-
9	NO. 1 INSTRUMENT PANEL GARNISH SUB-ASSEMBLY	55011A	-	-	-
10	AUTO HIGH BEAM SWITCH	84153	-	-	-

*A	w/o Knee Airbag	*B	w/ Knee Airbag
----	-----------------	----	----------------

## PROCEDURE

### 1. REMOVE FRONT DOOR SCUFF PLATE LH

Click here [INFO](#)

### 2. REMOVE COWL SIDE TRIM BOARD LH

Click here [INFO](#)

### 3. REMOVE NO. 1 INSTRUMENT PANEL UNDER COVER SUB-ASSEMBLY

Click here [INFO](#)

### 4. REMOVE LOWER CENTER INSTRUMENT PANEL FINISH PANEL (w/o Knee Airbag)

Click here [INFO](#)

### 5. DISCONNECT FRONT DOOR OPENING TRIM WEATHERSTRIP LH

Click here [INFO](#)


### 6. REMOVE INSTRUMENT SIDE PANEL LH

Click here [INFO](#)

### 7. REMOVE LOWER INSTRUMENT PANEL FINISH PANEL ASSEMBLY

Click here [INFO](#)


### 8. REMOVE INSTRUMENT CLUSTER FINISH PANEL ASSEMBLY


	Click here <a href="#">INFO</a>
---	---------------------------------

### 9. REMOVE NO. 1 INSTRUMENT PANEL GARNISH SUB-ASSEMBLY

Click here [INFO](#)

### 10. REMOVE AUTO HIGH BEAM SWITCH



	Remove in this Direction	-	-
---	--------------------------	---	---

