


Last Modified: 12-04-2024	6.11:8.1.0	Doc ID: RM100000029ZW3
Model Year Start: 2023	Model: Prius Prime	Prod Date Range: [12/2022 -]
Title: HEATING / AIR CONDITIONING: ROOM TEMPERATURE SENSOR: REMOVAL; 2023 - 2024 MY Prius Prius Prime [12/2022 -]		


REMOVAL




CAUTION / NOTICE / HINT

COMPONENTS (REMOVAL)



	PROCEDURE	PART NAME CODE			
1	STEERING WHEEL POSITION	-	INFO	-	-
2	NO. 3 STEERING WHEEL LOWER COVER	45187	INFO	-	-
3	NO. 2 STEERING WHEEL LOWER COVER	45186	INFO	-	-
4	LOWER STEERING COLUMN COVER	45287	INFO	-	-
5	UPPER STEERING COLUMN COVER	45286B	-	-	-



PROCEDURE		PART NAME CODE			
6	FRONT DOOR SCUFF PLATE LH	67914	-	-	-
7	COWL SIDE TRIM BOARD LH	62112	-	-	-
8	NO. 1 INSTRUMENT PANEL UNDER COVER SUB-ASSEMBLY	55606	-	-	-
9	LOWER CENTER INSTRUMENT PANEL FINISH PANEL	55434B	-	-	-
10	LOWER CENTER INSTRUMENT CLUSTER FINISH PANEL SUB-ASSEMBLY	55406B	-	-	-
11	COOLER (ROOM TEMP. SENSOR) THERMISTOR	88625Q	-	-	-

*A	w/ Knee Airbag	-	-
----	----------------	---	---

PROCEDURE

1. STEERING WHEEL POSITION



Click here [INFO](#)

2. REMOVE NO. 3 STEERING WHEEL LOWER COVER



Click here [INFO](#)

3. REMOVE NO. 2 STEERING WHEEL LOWER COVER



Click here [INFO](#)

4. REMOVE LOWER STEERING COLUMN COVER



Click here [INFO](#)

5. REMOVE UPPER STEERING COLUMN COVER

Click here [INFO](#)

6. REMOVE FRONT DOOR SCUFF PLATE LH (w/ Knee Airbag)

Click here [INFO](#)

7. REMOVE COWL SIDE TRIM BOARD LH (w/ Knee Airbag)

Click here [INFO](#)

8. REMOVE NO. 1 INSTRUMENT PANEL UNDER COVER SUB-ASSEMBLY (w/ Knee Airbag)

Click here [INFO](#)


9. REMOVE LOWER CENTER INSTRUMENT PANEL FINISH PANEL


Click here [INFO](#)

10. REMOVE LOWER CENTER INSTRUMENT CLUSTER FINISH PANEL SUB-ASSEMBLY

Click here [INFO](#)

11. REMOVE COOLER (ROOM TEMP. SENSOR) THERMISTOR



	Remove in this Direction	-	-
---	--------------------------	---	---

